
			7098048		6128323		P.H.	TEMP	Merry Cor
		Name and Address of the Owner, where	Influen (g	allons)	Effluent (gallo	(A10)			
1000	1900	Operator trutials	Total	Daty	Total	Daily		Commun	
Date	Time SD 0 %	C.C	1000550	2500	613341	4818	7-6 7.0	16712700	50 45
1-30-11	6:30	ce	7105124	4576	6137964	4623	7.6	16.50	48 30
2-30-11	600	LE	711 0097	4971	6142784	4772	7.6	14.6" 4	47 F 16
4-Jul-11	6:44	0.4	711 4514	6419	614 7516	4860	7.4	16.7°C	45 43
5-Jul-11	6,30	ce	7/2 /837	5323	615 2332	4742	1.5	16.80%	43 2
6-346-11	6:30	CE	712 6911	5072	615 7083	4745	7.6	14.8"	40 F 1
7-30-11	8:30	er	7130204	3295	Lack 2410	3867	7.6	16.740	34
8-Jul-11	7:30	ce	1133360	3154	617 1931	5454	7.4	14.10-	37
9-Jul-11	7:00	a	713 6355	2995	417 7397	-11/1-1-	7.4	14.400	35 F
10-Jul-11	9:00	04	7140002	39 13	1018 1471	54074	7.6	16.5"	33
11-Jul-11	6.00	ce	714 3915	3244	618 6277	4800		17.307	31 6
12-Jul-11	6.30		714 7159	2426	619 0375	4098	7.7	17.2°C	30 F
13-Jul-11	11:30	a	715 1985	2400	619 5197	4822		17.102	
14-Jul-11	7:30	ce	715 5242	3237	6200117	492:		17.00	
15-Jul-11	7:30	ce	715 7811	2577	1020 5 840	572	7.7	17.3"0	24
16-Jul-11	8:30	æ	715 9775	1956		419	7.7	17.40	13
17-Jul-11	7:00	Q.E	716 3916	4141	421 5482	545		18.00	12
18-Jul-11	10:00	ce	714 5061	1153	421 9420	3731		18.20	20
19-Jul-11	630	Cc	714 6819	1810	622 4289	4860	7.5	10.1	e 19
20-Jul-11	10 45	24	716 9580	2701	622 8957	4670	0 1.5	3.9.22	
21-Jul-11	THE NAME OF THE OWNER,						-		
22-308-11							-		
23-Jul-11						1			
24-Jul-11	1								
25-Jul-11	-								
26-Jul-11									
27-Jul-11									
28-Jul-11	1			1		1	_		
29-Jul-11				7		1	-		
30-Jul-11									
31-JUE11									

Figure 1. Log sheet for Jug Mountain Ranch SBR treatment system (July).



TRIM Record: 2011AGF2111

Figure 2. Cover of permittee's QAP.

Jug Mountain Ranch Resort Appendix 1: Photo Log Inspection Date: 7/21/2011

Page **1** of **16**



Figure 3. Operational manuals for the system and other reports and records.



Figure 4. Onsite laboratory facilities.

ID-002802-9 Inspection Date: 7/21/2011 TRIM Record: 2011AGF2111 Page **2** of **16**



Figure 5. Coagulant addition (far right), UV disinfection system (center), methanol addition (left).



Figure 6. Equipment and analytical sample container storage.

Inspection Date: 7/21/2011 Jug Mountain Ranch Resort ID-002802-9 Appendix 1: Photo Log TRIM Record: 2011AGF2111

Page **3** of **16**



Figure 7 Methanol addition with analytical sample container storage on shelves to left.



TRIM Record: 2011AGF2111

Figure 8. Coagulant addition with plant control terminal behind.



TRIM Record: 2011AGF2111

Inspection Date: 7/21/2011

Page **6** of **16**

Figure 9. Influent flow meter.



Figure 10. Close-up of lamp intensity gauge for in-line UV disinfection system. Top lamp is relatively new while bottom one shows lessening of intensity due to fouling. Operator has replacement lamps on hand.



TRIM Record: 2011AGF2111

Figure 11. Access hatches for both SBRs.

Jug Mountain Ranch Resort Appendix 1: Photo Log Inspection Date: 7/21/2011 Page **7** of **16**



Figure 12. Exterior of operational building.



Figure 13. SBR splitter box. Influent sampling point.

Inspection Date: 7/21/2011 ID-002802-9 TRIM Record: 2011AGF2111

Page **8** of **16**



Figure 14. Activated sludge pumps for reacting stage of treatment.



Figure 15. Settling stage of treatment.

ID-002802-9 Inspection Date: 7/21/2011 TRIM Record: 2011AGF2111 Page **9** of **16**



Figure 16. Decanting phase valves.



Figure 17. Plant effluent sampling point prior to disinfection.

ID-002802-9 TRIM Record: 2011AGF2111 Inspection Date: 7/21/2011 Page **10** of **16**



Figure 18. Upflow sand filter.

Page **11** of **16**



TRIM Record: 2011AGF2111

Inspection Date: 7/21/2011

Page **12** of **16**

Figure 19. Air compressor.



Figure 20. Sand filter control panel.



Figure 21. Sampling point for bacteriological samples (located after UV disinfection).

Inspection Date: 7/21/2011 ID-002802-9 TRIM Record: 2011AGF2111

Page **13** of **16**



Figure 22. Manhole cover for effluent from treatment plant.



Figure 23. Interior of effluent manhole showing discharge pipe from treatment plant.

ID-002802-9 Inspection Date: 7/21/2011 TRIM Record: 2011AGF2111 Page **14** of **16**



Figure 24. Discharge point is located in Cold Creek (area of high-density trees and bushes) approximately 100 feet from manhole. The upstream sample is taken approximately 200 feet upstream (to the left) of the discharge point.

TRIM Record: 2011AGF2111

Inspection Date: 7/21/2011

Page **15** of **16**




Figure 25. Discharge sampling point (inlet to Carey Pond). Vegetation at rear of photo is on a beaver dam which is periodically perforated by facility personnel.

TRIM Record: 2011AGF2111